FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re. G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

- Name of the officer
- Name of School
- Location with name of Educational District / Sub-District
- Classification of building as specified in column 4 of the application for fitness certificate and size
- 2023-24 Period for which the certificate is issued
- Nature of defect, if any:
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought and put up
 - e) Roof
 - Flooring
 - Miscellaneous (Cracks etc.)

- Any major defects noticed which will render the building unsafe in any manner
- Whether maintenance works have been done properly

1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood ctc.

> 2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate

Singly Devi. C.S Infant Jesus Public School Kidangood

Pala, Kidangood

Permenent Building RCC Germenent Building RCC told - 6 x 6.30 x 631 x 3.60m. told - 1 x 7.90 x 6.20 x 3.60m. F. F - bx b. 30 x b. 31 x3-68 - 1 x 6. 30 x 4 95 x 3.60 56 - Library - 1 x 9 . 6213295 56 - Library - 1 x 9 . 6213295 11 Lab - 1 x b . 29 1 4 . 93 x 3

Whether the structure is sound or not for conduct- Sound under normal weather ing classes.

Londitions of Kerala.

Certified that the school was inspected by me on 09 66 2023 and found to be fit unfit to 2000 - DATENO conduct classes for the period.....

for the reasons stated above ER

Place Kidsnz.ag Date ... D. 9. Jab. 1.20.23 Kidengoor GP